DECKBRITE™

WOOD CLEANER & COATING PREP

DESCRIPTION AND USES

Wolman DeckBrite Wood Cleaner & Coating Prep is an oxygenated powder concentrate cleaner for weathered wood and a coating preparation for new wood. When mixed with water, DeckBrite quickly and safely restores dirty, weathered-gray, mildew and algae-stained wood to its bright, natural, like-new look. In just 10 minutes, its unique, oxygen-powered foaming action deep cleans and removes stains without damaging the wood's cell structure or leaving a bleached out appearance. DeckBrite also clears away traces of old water sealers from weathered wood and invisible coating barriers (such as "mill glaze" or excess surface wax) from new wood, enabling proper adhesion or penetration of protective coatings. Plus, the 100% biodegradable, acid and chlorine-free solution is harmless to surrounding plant life.

FEATURES

- Non-Toxic, DIY Friendly Cleaning Solution – safest alternative for you, your wood and your yard.
- Ultra-Oxidizer – strongest wood cleaner of its kind.
- Clings to Vertical Surfaces for effective cleaning the first time around.
- Neutralizer Not Required – saves time and effort.

PRODUCT

SKU	
16001	1 lb. Pouch makes 2-1/2 gallons solution
16003	2.25 lb. Canister makes 5 gallons solution

RECOMMENDED USES

FOR EXTERIOR USE ONLY

Use to prepare or restore outdoor wood decks, porches, fences, siding, shakes & shingles, outdoor furniture & décor, boat docks, boardwalks, gazebos & arbors, play sets and more. Removes the Following Coating Barriers from weathered wood: Ground-In Dirt, Mildew, Mold & Algae Stains, Weathered Gray Surface, Old Sealers & Clear Finishes

WOOD TYPES: Use on all types of pressure-treated lumber, plastic and wood composite materials, North American hardwoods such as Poplar and Hickory, and weathered Cedar and Redwood. (For new Cedar, Redwood or exotic hardwoods, use Wolman Deck & Fence Brightener Liquid Concentrate).

Note: New generation (non-CCA) pressure-treated lumber, when initially installed may develop pronounced mildew growth during the first few months of weathering. To reduce or avoid mildew staining allow wood to weather for 1 to 3 months before applying a protective coating. To immediately protect against water damage, prep the surface with DeckBrite and pre-treat with Wolman RainCoat® Clear Water Repellent – Oil-Base. Allow 6 months before applying a protective coating.

PRODUCT APPLICATION

Mixing:
Mix ¾ cup powder per one (1) gallon lukewarm tap water. Solution will foam and appear bright blue. Stir occasionally and wait for approximately 5 minutes for powder to dissolve. If using cold water, a few more minutes may be necessary. When blue color disappears, powder is completely dissolved, and *DeckBrite* solution is ready to apply. Use within 6 hours of mixing. Do not mix with any other products.

Make sure entire wood surface is dry and free of dust, dirt and debris. If the surface is hot to the touch or in direct sunlight, dampen with fresh water to cool. Apply when outside temperatures are above 40°F.

Apply:
Pre-wet surface with fresh water. Working on 20 sq. ft. at a time to maintain optimum surface wetness, apply solution and let sit and foam for 10 minutes. If solution dries prematurely, keep it wet with additional solution as needed.

On horizontal surfaces: Apply solution with a pump sprayer, airless sprayer, brush, mop or roller. On vertical surfaces: Apply solution with a pump sprayer or deep-nap roller, working from the bottom to the top of the structure.

Coverage Rate – Depending on wood age and species, surface porosity, method of application, one (1) gallon of solution covers approximately 150 sq. ft.

Brush or Pressure Wash:
Brush: Briefly scrub surface with Wolman WOODWORX® Deck Brush or other stiff, short-bristle brush, using moderate pressure when brushing.
Pressure wash: Use a 40° tip and 1,500-2,500 PSI for pressure-treated wood and hardwood, 500-1,000 PSI for Cedar and Redwood. Move lengthwise with boards to avoid cut marks across grain. Either technique helps ensure old surface is entirely removed.

Rinse:
If pressure washing is not employed, after brushing, rinse thoroughly with a garden hose, using the highest pressure nozzle setting available. On a vertical surface, continually rinse brightened areas to avoid streaking. Rinse any wood fibers off surrounding surfaces immediately. When dry, wood surface should appear clean, bright and free of mildew and algae stains.

Recommended Number of Coats – Apply one (1) coat, and allow to sit and foam for entire recommended time of 10 minutes. Heavily weathered, extremely dirty or badly stained areas may require a second application.

CAUTION: Bare wood and/or coated surfaces can become slippery when wet. Use caution when walking on wet surfaces.

Form: JPB-17
Rev.: 082613

HANDLING AND STORAGE

Clean Up:
Clean tools and equipment after use with water.

Wolman DeckBrite, in diluted form, is virtually non-irritating to skin and eyes, and contains no acids or chlorine bleach. While the diluted solution will not harm plant life, rinse with water after exposure to remove dried residue. Do not store prepared solution in airtight containers to avoid excess pressure buildup. Do not mix or use with products containing chlorine bleach (sodium hypochlorite).

Storage:
Store unused concentrate in the closed, original labeled container.

Precautions:
DANGER! Powder is severely irritating to eyes. Contains sodium percharbonate. Prevent contact with eyes and prolonged contact with skin. Use eye protection when handling powder or severe eye injury may result. Harmful if swallowed. Store unused powder in original container and away from combustible materials.

KEEP OUT OF REACH OF CHILDREN.

Compatibility:
This product will clean but not remove oil or latex stains and paints which are in sound condition. This product is harmless to most plant life as well as plastic, glass, Plexiglas, brick, aluminum and vinyl siding, metal, concrete and caulked surfaces. Rinse plants and surrounding surfaces with water after exposure. Once dry, surfaces cleaned with this product may be coated with oil or water-base water repellants, transparent finishes, colored stains or paints.

PHYSICAL PROPERTIES

Physical Properties	Oxygenated powder concentrate
Active Ingredient	Sodium Percarbonate
Ph in solution	10.5
Theoretical Coverage	Depending on wood age and species, surface porosity and method of application, one (1) gallon of solution covers approximately 150 sq. ft.
Application Parameters	Minimum 40°F
Dry Time	Allow wood to dry thoroughly before applying a water based finish. Allow a minimum of 24 hours before applying oil based stain or finish.
Biodegradable	Biodegrades to oxygen, water and soda ash
Toxicity	Classified by FDA as Generally Recognized As Safe (GRAS)

The technical data and suggestions for use contained herein are correct to the best of our knowledge, and offered in good faith. The statements of this literature do not constitute a warranty, express, or implied, as to the performance of these products. As conditions and use of our materials are beyond our control, we can guarantee these products only to conform to our standards of quality, and our liability, if any, will be limited to replacement of defective materials. All technical information is subject to change without notice.