· TRUSTED QUALITY SINCE 1921 ·
RUST-OLEUM®
SPECIALTY

RUST-OLEUM® SPECIALTY FOAM PRIMER

DESCRIPTION AND USES

Rust-Oleum® Specialty Foam Primer allows craft foam to be painted with aerosol paints without damage. Foam Primer covers, protects and primes foam to reduce melting when aerosol paint is applied on top. Foam Primer is recommended for craft and floral foam.

PRODUCT

SKU	DESCRIPTION (Aerosol)
331045	Foam Primer 12 oz.

PRODUCT APPLICATION

PAINTING CONDITIONS

Use outdoors or in a well ventilated area. Use when temperature is between 50-90°F (10-32°C) and humidity is below 65% to ensure proper drying. Avoid spraying in very windy and dusty conditions. Cover surrounding area to protect from spray mist.

SURFACE PREPARATION

Surface should be clean and in sound condition. If necessary, remove all dirt, grease, oil, salt and chemical contaminants by washing the surface with soap and water, or other suitable cleaning method. Rinse with fresh water and allow to thoroughly dry.

WARNING! If you scrape, sand or remove old paint from any surface, you may release lead paint dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE; ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

PRODUCT APPLICATION (cont.)

APPLICATION

Shake can vigorously for one minute after the mixing ball begins to rattle. If mixing ball fails to rattle DO NOT STRIKE CAN. Contact Rust-Oleum. Hold can upright 10-16" from surface and spray in a steady back and forth motion, slightly overlapping each stroke. Keep the can the same distance from the surface. Keep the can in motion while spraying. Apply two or more light coats a few minutes apart to avoid drips and runs. **Do not use near open flame.**

DRY & RECOAT

Dry and recoat times are based on 70⁰F (21°C) and 50% relative humidity. Allow more time at cooler temperatures. Dries to the touch in 30 minutes, and fully dry in 24 hours. May recoat in 1 hour or when Foam Primer is fully dry.

CLEAN-UP

Clean valve immediately after use by turning can upside down and depressing spray button for 3-5 seconds (some paint will be sprayed out, so be careful to not inadvertently spray yourself or other objects). Clean up wet paint with xylene or mineral spirits. Properly discard empty container. Do not burn or place in home trash compactor.

CLOGGING

If the valve clogs, twist and pull off spray tip and rinse in a solvent such as mineral spirits. Do not insert any object into can valve opening.

RUST-OLEUM® SPECIALTY FOAM PRIMER

PHYSICAL PROPERTIES

		FOAM PRIMER
Resin Type		Hydrocarbon
Pigment Type		Titanium Dioxide, Talc
Solvents		Acetone, Naptha, Xylene
MIR		0.70 Max
Fill Weight		12 ounces
Recommended Dry Film Thickness (DFT) per coat		1.5-2.0 mils
Dry Times at 77°F (25ºC) and 50% Relative Humidity	**Touch**	30 minutes
	Recoat	1 hour
	Handle	2 hours
	Full Cure	24 hours
Shelf Life		12 months
Safety Information		For additional information, see SDS

Calculated values are shown and may vary from the actual manufactured material.