

APPLIANCE FPOXY is an ultra-hard, moisture resistant enamel that is specifically or inducted for indoor metal surfaces. It provides a smooth, washable surface for or effinishing the exterior of appliances such as refrigerators, dishwashers, laundy or machines, dryers and other indoor metal applications (cabinets, tables).

READ ALL INDECTIONS IRSTET EFFORE FERDINNIES PROJECT.

Painting Conditions: Use outdoors or in a well-ventilated area such as an open garage. Use when temperature is between 50°F (10°C) and 90°F (32°C) and humidity is belowed. 65% to ensure poper drying. Not intended for continuous water submersion or for surfaces that, when heated, exceed 200°F (93°C). Priming is not recommended. Avoid spraying in very windy, dusty conditions. Cover surrounding area to protect from syry mist. Do not use on objects exposed to heat (eg., stovetops, oven interiors, etc.)

mist. Do not use on objects exposed to heat (eg., stovetops, over interiors, etc.)

Preparation: Remove loose plant and rust with wire brush or sandpaper. WARNING If you scrape, sand or remove old plant, you may release lead dust. LEAD IS TOXIC. Contact the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead. Lightly sand glossy surfaces. Clean with soap and water, rinse and let dry.

Painting. Shake can vigorously for one minute after mixing ball begins to rattle. Shake often during use. If mixing ball falls to rattle ON DYSTRIKE CAN. Contact Nust-Gleum. Hold can upright 12-16 "from surface and spray in a steady back-and-forth motion, slightly overlapping each stoke. Keep the can the same distance from the surface. Keep the can the same distance from the surface. Keep the can be can be considered to the same motions.

the can in motion while spraying.

Dry & Recoat Times based on 70 F – 50% relative humidity, Allow more time at cooler temperatures. Dries to the touch in 2-4 hours, to handle in 5-9 hours and fully dry in 24 hours. May recoat within 1/2 hour or after 1 week.

Clean-up: When finished snaving, clear spray valve by turning can upside down and pushing spray button for 5 seconds. Clean up wet paint with Xylol or mineral spirits. Throw away empty can in trash pictup, Do not burn or place in home trash compactor. Clogging: If valve clogs, twist and pull off spray tip and rinse it in a solvent such as mineral spirits. Do not stock pin or other object into the stem.

CONTAINS: LIQUETED PETROLEUM GAS., POUTYL ACETATE, ACETONE, DIMETHYL CARBONATE, AROMAITE MYDROCARBONKS and PETROLEUM DISTILLATES. (Apport harmini, May after the brian or nervous system causing dizzines, headardh or maisse, Causes eye, skin, nose and throat imitation. Do not puncture, strike, or incinerate (burn) container. Exposure to heat or prolonged excussive to south may cause bursting, bo not depaste to heat or store at temperatures above 1207-4207, NOTICE. Peopors tave associated repeated and prolonged occupational missise by deliberately solvent in the content of the content may be harmful or fatal. Vapors may ignite explosively, Keep away from theat, sparks and flame. Do not smoke. Entinguist all flames and plot lights and turn off stoves, heaters, electric motions and other sources of ignition during use and until all vapors are gener. Pervent field up of vigoros by opening all vanious vanidors to achieve cross-ventilation. Use only with adequate ventilation. Do not breathe dust, apors or spray mist. Ensure fresh are entry during application and drying. If you experience eye valering, headards or dezines, were entry during application and drying. If you experience eye valering, headards or dezines, were entry during application and drying. If you experience eye valering, headards or dezines, were entry during application and drying. If you experience difficulty is breathing, leave the area to obtain fresh air, if continued with fairny of water for at least 15 minutes and general development of the continued with fairny of water for at least 15 minutes and general development of the provision, local poison control center or local emergency roun. For product health intolination, call your physician, local poison control center or local emergency roun. For product health intolination, call your physician, local poison control center or local emergency roun. For product health intolination.

SATISFACTION GUARANTEED: If you are dissatisfied with this product, contact Rust-Oleum Product Support at 800-481-4785 for product replacement or a full refund of the purchase price. Refer to product number and batch code.

RUST-OLEUM

11 Hawthorn Pkwy., Vernon Hills, IL 60061 800-481-4785 rustoleum.com

Made in USA | Hecho en E.U.A. ©2017 Rust-Oleum Corporation 331438 0817 LEA TODAS INSTRUCCIONES PRIMERO ANTES DE EMPEZAR EL PROYECTO.

Condiciones para Pintado: Use en el exterior o en un área bien ventilada como un garaje abierto. Use cuando la temperatura se encuentra sobre 10°C (50°F) y la humedad debajo de un 65% para asegurar un secado apropiado. No sirve para uso en sumersión continua bajo aqua o para superficies que son calentada: hasta una temperatura que excede 93°C (200°F). No se recomienda la aplicación de una primera capa para la preparación de la superficie. Evite la aplicación usando rociado cuando existen condiciones con mucho viênto o polvo. Cubra el área circundante para protegería contra la niebla del rociado. No use en objetos la pintura suelta y la oxidación usando un cepillo de alambre o papel lija. ¡ADVERTENCIA! Si raspa, lija c remueve la pintura vieja, usted puede soltar polyo de plomo. EL PLOMO ES TOXICO, Póngase en contacto con la Línea Abierta Nacional para la Información Sobre el Plomo llamando al 1-800-424-LEAD o visite al sitio www.epa.gov/lead. Lijé levemente las superficies lustrosas. Limpie con jabón y agua, enjuague y deje secar. Pintado: Agite la lata vigorosamente por un minuto después de haber escuchado el sonido de la bolita mezcladora. Agite a menudo durante el uso. Si la esfera no hace ruido, NO GOLPEE LA LATA Póngase en contacto con Rust-Oleum. Agarre la lata derecha como a 12-16 pulgadas desde la superficie y ročié usando un movimiento de arriba para abajo, asegurando que cada nueva pasada trastapa la anterior Mantenga la lata a la misma distancia desde la superficie. Mantenga la lata en movimiento durante todo el rociado. Aplique dos o más capas delgadas unos pocos minufos aparte. Tiempo de Secado y para Aplicación de Otra Capa a una temperatura de 21°C y una humedad relativa de un 50%. Permita más bempo en temperaturas más frías. Seca al tado en 24 horas, se puede aparar en 59 horas y se encuentra completamente seca en 24 horas. **Se peuede aplicar otra capa dentro de 1/2 hora o después de 1 semana.** Limpieza: Al acabar de rociar, limpie las velvula volcando la tata de arriba para abajo y empujando el botón per 5 segundos. Limpieza de la pintura húmeda con Xilol o espíritus minerales. Deseche la lata vacía en el basurero. No queme o ponga en un compactador doméstico para basura. Atascal la válvula se atasca, haga girar y jale el aspersor (botón para rociar) y enjuáguelo con un solvente como espíritus de mineral. No inserté un affiler o cualquier otro objeto dentro de la espiga

CONTIENE: GAS DE PETROLEO LICUADO, n-ACETATO DE BUTILO, ACETONA, DMC HIDROCARBONS AROMATICOS Y DESTILADOS DE PETROLEO. Vadores dañinos, Pueden afectar al cerebro o al sistema nervioso causando mareos, dolores de cabeza, o nausea Causan irritaciones en los ojos, piel, nariz y la garganta. No perfore golpee o incinere (quemar el contenedor. Una exposición al calor o una prolongada exposición al Sol puede causar ruptura explosiva. No exponga al calor o almacene en temperaturas sobre 48°C (120° F AVISO: Los reportes han asociado una exposición excesiva ocupacional repetida y prolongada a los solventes con daños permanentes al cerebro v al sistema nervioso. Un malfuso intencional al deliberadamente concentrando y respirando el contenido puede ser dañino: fatal, **Los vapores pueden encenderse explosivamente.** Mantenga lejos del calor, chispas / las llamas. No fume. Apague las llamas y llamas pilotos, y apague las estufas, calentadores motores eléctricos y todas las otras fuentes de ignición hasta que todos los vapores hayar desaparecido, Prevenga la acumulación de vapores abriendo todas las ventanas y puertas para lograr una ventilación cruzada. **Use solamente con una ventilación adecuada**. No respire el polvo, los vapores o la niebla del rociado. Asegure la entrada de aire fresco durant la aplicación y el secado. Si experimenta lagrimeo de los ojos, dolores de cabeza, o mareos use protección para la respiración (aprobada por NIOSH) o salga del área. Evite contacto con los ojos, piel, y la ropa, **Primeros Auxilios:** Si es que sufre una dificultad al respirar salga del área para óbtener aire fresso. Si continua sufriendo una dificultad al respirar obfenga inmediatamente asistencia médica. En caso de contacto con los oios, eniuaque inmediatamente con bastante agua por 15 minutos por lo menos y obtenga atención médica. Para contacto con la piel, lave completamente con jabón y agua.

ADVERTENCIÁ: Cáncer y daños regroductivos -www.P65Warnings.ca.gov. MANTENGA FUERA DEL ALÇANCE DE LOS NIÑOS. En caso de emergencia, comuníquese con su médico, centro local para el control de venenos o clínica para emergencias. Para obtener más información sobre el producto v los posibles efectos en la salud. Hame al (800) 481-4785. PROHIBIDA SU VENTA A MENORES DE EDAD: PRODUCTO ORIGINARIO DE E.U.A

