

GRAY PRIMER

8781

• TRUSTED QUALITY SINCE 1921 •

RUST-OLEUM®



LATEX ALUMINUM PRIMER

FOR THE
**ULTIMATE
FINISH**
ON ALUMINUM OR
GALVANIZED SURFACES

32 FL. OZ. (1 QT.) .946 L

CAUTION!
MAY CAUSE DELAYED
EYE AND SKIN IRRITATION.
See Other Cautions On Back Panel

ADVERTENCIA!
PUEDE CAUSAR REACCIONES
RETRASADAS EN
LOS OJOS Y LA PIEL.
Ver al dorso precauciones adicionales.

RUST-OLEUM® Stops Rust® Latex Aluminum Primer is a specially formulated base coat for aluminum or galvanized metal. It provides a tight bond for the top coat, thus resisting the usual problem of blistering, baking or peeling paint. This latex primer cleans up easily with soap and water and dries quickly. The end result is a paint finish that lasts longer and looks better.

Directions: Use when temperature is between 50°F (10°C) and 100°F (37.7°C) and humidity is below 85% to ensure proper drying. Remove loose paint with a wire brush, scraper or sandpaper. Clean surface with soap and water. For oily surfaces, scrub with a strong detergent solution. Rinse and dry surface. **WARNING:** If you scrape, sand or remove old paint, you may release lead dust. (LEO) 10% LEAD. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMAN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-434-5640 or log on to www.epa.gov/lead. Stir thoroughly. Thinning is not required. In hot, dry conditions you may thin up to 5-10% with water to extend workable brushing time. Use a good quality brush or roller. Avoid excessive brushing as this will reduce film thickness and protection. Use light, even brush strokes to ensure proper coverage and the smoothest finish. If using a roller, cover approximately one square yard at a time. Roll away from previously coated area and work back to it for a uniform appearance. Dries to the touch in 1-2 hours at 70°F (21°C) and 50% relative humidity. Dries to handle in 24 hours. Recoat in 24 hours.

If finish coat is:
Brush-on Latex Enamel _____ Allow to dry for at least:
Brush-on Oil-Based Enamel _____ 1-2 Hours
Aerosol _____ 24 Hours
Aerosol _____ 16-24 Hours

Clean, brush, roller and other tools with soap and water immediately after use. Enamels are not recommended for water immersion.

Contains: Acrylic Resin. Avoid breathing dust, vapors or spray mist. Ensure fresh air entry during application and drying. If you experience eye irritation, headache or dizziness or if air monitoring demonstrates vapor/mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH/MSHA approved) during and after application. Follow respirator manufacturer's directions for respirator use. Close container after use. Wash thoroughly after handling.

First Aid: In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention. For skin, wash thoroughly with soap and water. If you experience difficulty breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately. If swallowed, do not induce vomiting. Get medical attention immediately.

KEEP OUT OF REACH OF CHILDREN.

KEEP FROM FREEZING.

Unlabeled— Safe for use on children's toys, furniture, etc.

Maximum VOC content of 250 grams per liter
(2.08 lbs/gal).

We stand behind our products. If you are dissatisfied with this product, contact our Customer Service Department for a refund of the product purchase price.

Contains: Resins Acrylic. Evite respirar el polvo, los vapores y la niebla del rociado. Asegure la entrada de aire fresco durante la aplicación y el secado. Si experimenta irritación de los ojos, dolores de cabeza o mareo, o si el monitoreo del aire detecta niveles de vapor o niebla superiores a los límites apropiados, póngase correctamente una máscara respiratoria adecuada (aprobada por NIOSH o MSHA) durante y después de la aplicación. Siga las instrucciones del fabricante de la máscara respiratoria. Cierre el contenedor después de usar el producto. Lávese bien después de manejarse.

PRIMEROS AUXILIOS: En caso de contacto con los ojos, lávelos inmediatamente con abundante agua por lo menos 15 minutos y busque atención médica. En caso de contacto con la piel, lave la área afectada con jabón y agua. Si experimenta dificultad al respirar, abandone el área y respire aire fresco. Si la dificultad continúa, obtenga atención médica inmediatamente. En caso de ingestión, no se induzca vómito. Llame un médico inmediatamente.

MANTÉNGALO FUERA DEL ALCANCE DE LOS NIÑOS.

EVITE LA CONGELACIÓN DEL PRODUCTO.

No contiene plomo — Se puede usar en juguetes de niños, muebles, etc.

8781504 LATEX ALUMINUM PRIMER



RUST-OLEUM®
CORPORATION

11 Hawthorn Parkway, Vernon Hills, IL 60061

rustoleum.com 1-800-481-4785

npm Company

©2007 Rust-Oleum Corporation Made in USA 2004080407

0 20066 87815 3