



**CORPORATION**

www.rustoleum.com

11 Hawthorn Pkwy., Vernon Hills, IL 60061 1-877-815-2536



## METAL CLEAN & ETCH

### Directions for Use:

**ONE STEP PROCESS:** Save time on most paint projects by cleaning and etching all in one step. For heavily soiled surfaces the Original KRUD KUTTER should be used as a pre-prep step, to remove excess oil, grease, and dirt. Excess rust should be removed with a wire brush.

1. Mix 1 part of concentrate with 3 parts water in a plastic container. On heavily rusted areas mix with 2 parts water.
2. Apply the premix to metal surface with paintbrush, spray bottle, sponge, or pump up sprayer.
3. Allow the premix to remain on the surface for up to 10 minutes, then thoroughly rinse with water, and wipe dry with rags.
4. Make sure the metal is completely clean and dry, then paint treated surface within 48 hours, to prevent formation of new rust.

**If you have any questions or concerns regarding this product please contact Krud Kutter customer support at (800) 466-7126**