

• TRUSTED QUALITY SINCE 1921 •

# RUST-OLEUM®

# Chalked

## ultra matte paint



# CHARCOAL

## DRIES TO A CHALKY SMOOTH FINISH

### easy application /// superior coverage

### sandable

**DANGER!** EXTREMELY FLAMMABLE LIQUID & VAPOR.  
VAPOR HARMFUL. VAPORS MAY CAUSE FLASH FIRE.  
CONTENTS UNDER PRESSURE.  
See other cautions on back panel.

## NET WT. 12 OZ (340 g)

**¡PELIGRO!** LÍQUIDO Y VAPORES EXTREMADAMENTE  
INFLAMABLES. VAPORES NOCIVOS. PUEDEN CAUSAR UN INCENDIO  
REPENTINO. NO SOMETER A PRESIÓN.  
Observar otras precauciones al dorso.



**Rust-Oleum® Chalked Ultra Matte Paint creates an ultra matte finish with superior coverage and adhesion. It transforms and rejuvenates furniture and home decor with a most matte finish. Rust-Oleum® Chalked Ultra Matte paint provides one coat coverage on most surfaces with little to no prep or priming. It can be painted or distressed, giving any project a one-of-a-kind look. Use on wood, metal, ceramic, glass, canvas and more.**

**Painting Conditions:** Use outdoors or in a well-ventilated area such as an open garage. Use when temperature is between 50°F (10°C) and 90°F (32°C) and humidity is below 65% to ensure proper drying. Avoid spraying in very windy, dusty conditions. Cover surrounding area to protect from spray mist. Preparation: Remove loose paint and rust with a wire brush or sand paper. For superior adhesion, lightly sand glossy or porous surfaces. Remove any wax by lightly wiping surface with mineral spirits. Let dry. Clean with soap and water, rinse, and let dry. **WARNING!** If you scrape, sand or remove old paint, you may release lead dust. **LEAD IS TOXIC.** Contact the National Lead Information Hotline at 1-800-424-LEAD or log on to [www.epa.gov/lead](http://www.epa.gov/lead).

**Priming:** Priming is not required for most surfaces. For superior coverage, a Rust-Oleum® primer can be used for surfaces such as bare wood and treated wood. **Painting:** Shake can vigorously for one minute after mixing ball begins to rattle. Shake often during use. If mixing ball fails to rotate DO NOT STRIKE CAN. Contact Rust-Oleum®. Hold can upright 10-12" from surface and spray in a steady back-and-forth motion, slightly overlapping each stroke. Keep the can the same distance from the surface. Keep the can in motion while spraying. Apply 2 or more light coats a few minutes apart.

**Dry & Recoat Times:** based on 70°F - 50% relative humidity. Allow more time at cooler temperatures. May be recoated within 1 hour or after 48 hours. Dries to the touch in 20 minutes and to handle in 1 hour. Fully dry in 24 hrs. **NOTE:** On plastic maximum paint adhesion and durability is achieved in 5-7 days. Chalked protective coat can be applied for added protection. Apply according to instructions on can. **Clean-up:** Wipe off tip before storing. Clean up wet paint with Xyloil or mineral spirits. Throw away empty can in trash pickup. Do not burn or place in home trash compactor. **Clogging:** If valve clogs, twist and pull off spray tip and rinse it in a solvent such as mineral spirits. Do not stick pin or other object into the stem.

**Distressing:** This paint can be distressed if desired. To distress, lightly sand the surface with a fine-medium sand paper or a sanding sponge. The more the piece is distressed, the more the original surface will show through. Wait 2 hours before sanding or distressing.

**DANGER: CONTAINS: ACETONE, LIQUIFIED PETROLEUM GAS, PETROLEUM DISTILLATES AND AROMATIC HYDROCARBONS.** Vapor harmful. May affect the brain or nervous system causing dizziness, headache or nausea. Causes eye, skin, nose and throat irritation. Do not puncture, strike, or incinerate (burn) container. Exposure to heat or prolonged exposure to sun may cause bursting. Do not expose to heat or store at temperatures above 120°F (49°C). **NOTICE:** Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the content may be harmful or fatal. **Vapors may ignite explosively.** Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. **Use only with adequate ventilation.** Do not breathe vapors or spray mist. Ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness, wear respiratory protection (NIOSH approved) or leave the area. Avoid contact with eyes, skin and clothing. **First Aid:** If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately. In case of eye contact, flush immediately with plenty of water for at least 15 minutes and get medical attention; for skin, wash thoroughly with soap and water. **WARNING:** Cancer and Reproductive Harm - [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov). **KEEP OUT OF REACH OF CHILDREN. For emergency, call your physician, local poison control center or local emergency room. For product health information, call: (800) 481-4785.**

**SATISFACTION GUARANTEED:** If you are dissatisfied with this product, contact our Product Support Department at 1-800-481-4785 for a full refund of the purchase price. Refer to product number and batch code on bottom of can.

# RUST-OLEUM CORPORATION

11 Hawthorn Pkwy., Vernon Hills, IL 60061

800-481-4785 [rustoleum.com](http://rustoleum.com)

Made in USA | Hecho en E.U.A.

©2017 Rust-Oleum Corporation 334270 1117

**Condiciones para Pintado:** Use en el exterior o en un área bien ventilada como un garaje abierto. Use cuando la temperatura se encuentre entre 10°C (50°F) y 32°C (90°F) y la humedad del aire de un 65% para asegurar un secado apropiado. Evite la aplicación usando rodado cuando existen condiciones con mucho viento o polvo. Cubra el área circundante para protegerla contra la niebla del rodado. **Preparación:** Quite la pintura suelta y el óxido con un cepillo de alambra o papel de lija. Para una mayor adhesión, lije suavemente la superficie con solvente mineral. Deje seca. Limpie con agua y jabón, enjuague y deje seca. **¡ADVERTENCIA!** Si raspa, lija o quita pintura vieja puede desprenderse polvo de plomo. **EL PLOMO ES TOXICO.** Póngase en contacto con la Línea Abierta Nacional para la Información Sobre el Plomo llamando al 1-800-424-LEAD o visite al sitio [www.epa.gov/lead](http://www.epa.gov/lead) **Primer Capa:** No se requiere imprimación para la mayoría de las superficies.

Para lograr una mayor cobertura, puede utilizar un imprimador Rust-Oleum® en superficies lisas como Madera con y sin tratamiento. **Pintado:** Agite la lata vigorosamente por un minuto después de haber escuchado el sonido de la botella mezcladora. Agite a menudo durante el uso. Si la esfera mezcladora no hace ruido **NO GOLPEE LA LATA.** Póngase en contacto con Rust-Oleum®. Agite la lata derecha como a 10-12 pulgadas desde la superficie y rocíe usando un movimiento de arriba para abajo, asegurando que cada nueva pasada trascienda la anterior. Mantenga la lata a la misma distancia desde la superficie. Mantenga la lata en movimiento durante todo el rodado. Avance dos o más capas delgadas unas pocas minutos aparte. **Tiempo de Secado y para Aplicación de Otra Capa:** a una temperatura de 21°C (70°F) una humedad relativa de un 50%. Permita más tiempo entre aplicaciones más frías. Se puede aplicar otra capa dentro de 1 hora o después de 48 horas. Seca al tacto en la 20 minutos y se puede aparecer en 1 hora. **NOTA:** Sobre plástico la máxima adhesión y durabilidad de la pintura son largas en 5-7 días. Para obtener una mayor protección puede aplicar una capa protectora calcarea. Aplique de acuerdo a las instrucciones de la lata. **Limpieza:** Antes de almacenar limpie para despejar la válvula de la válvula de la pintura húmeda con Xyloil o espíritu de mineral. Deslice la lata vacía en un basurero. No quemar ni ponga la lata en un compactador doméstico para la basura. **Atascamiento:** La pintura se puede decapar o limpiar. Para decapar, lije ligeramente la superficie con una lija de papel fina de grano medio o una esponja de lija. Mientras más decapada este la pieza, mas se vera la superficie original. Espere dos horas antes de lijar o decapar.

**PELIGRO! CONTIENE: ACETONA, GAS LIQUIDO DE PETRÓLEO, DESTILADOS DE PETRÓLEO Y HIDROCARBUROS AROMÁTICOS.** Vapores dañinos. Pueden afectar al cerebro o al sistema nervioso causando mareos, dolores de cabeza, o náuseas. Causan irritaciones en los ojos, piel, nariz y la garganta. No perforar, golpear o incinerar (quemar) el contenedor. Una exposición al calor o una prolongada exposición al Sol puede causar ruptura explosiva. No exponga al calor o almacene en temperaturas sobre 49°C (120°F). **AVISO:** Los reportes han asociado una exposición excesiva ocupacional repetida y prolongada a los solventes con daños permanentes al cerebro y al sistema nervioso. Un mal uso intencional al deliberadamente concentrarlo y respirando el contenido puede ser dañino o fatal. **Los vapores pueden encenderse explosivamente.** Mantenga lejos del calor, chispas y las llamas. No fume. Apague las llamas y llamas piloto, y apague las estufas, calentadores, motores eléctricos y todas las otras fuentes de ignición hasta que todos los vapores hayan desaparecido. Prevenga la acumulación de vapores abriendo todos las ventanas y puertas para lograr una ventilación cruzada. **Use solamente con una ventilación adecuada.** No respire los vapores o la niebla del rodado. Asegure la entrada de aire fresco durante la aplicación y el secado. Si experimenta lagrimeo de los ojos, dolores de cabeza, o mareos, use protección para la respiración (aprobada por NIOSH) o salga del área. Evite contacto con los ojos, piel, y la ropa. **Piromens Avanzados:** Si es que sufre una dificultad al respirar, salga del área para obtener aire fresco. Si continúa sufriendo una dificultad al respirar, inmediatamente busque asistencia médica. En caso de contacto con los ojos, enjuague inmediatamente con bastante agua por 15 minutos por lo menos y obteenga atención médica. Para contacto con la piel, lave completamente con jabón y agua. **¡ADVERTENCIA!** Cáncer y datos reproductivos - [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov). **MANTENGA FUERA DEL ALCANCE DE LOS NIÑOS.** En caso de emergencia, comuníquese con su médico, centro local para el control de venenos o clínica para emergencias. **Contiene más información sobre el producto y los posibles efectos en la salud, llame al (800) 481-4785. PROHIBIDA SU VENTA A MENORES DE EDAD; PRODUCTO ORIGINARIO DE E.U.A.**

302590 CHARCOAL



0 20066 32631 9