Page 1 / 8 Date Printed: 11/08/2021

# Safety Data Sheet



www.rustoleum.com.au

## 1. Identification

SPECLT SSPR 6PK FARM GLOSS BLACK **Product Name: Revision Date:** 11/08/2021

**RUST-OLEUM FARM & IMPLEMENT GLOSS** Name on Label: **Supercedes Date:** 07/01/2020

**BLACK** 

**Product Identifier:** 280123

**Product Use/Class:** Topcoat/Aerosols

Rust-Oleum Australia & New Zealand Pty. **Rust-Oleum Corporation** Supplier: Manufacturer:

11 Hawthorn Parkway Level 2, 307 Ferntree Gully Road Vernon Hills, IL 60061

Mount Waverley, Victoria 3149 **USA** 

Australia Ph 1 300 784 476

Preparer: Regulatory Department

Emergency Telephone: 24 Hour Hotline: 1-300-366-961

## 2. Hazard Identification

This product is classified as a Dangerous Good per the Australian Code for the Transport of Dangerous Goods by Road and Rail. This product was assessed per Safe Work Australia criteria.

## Classification

#### Symbol(s) of Product









#### Signal Word Danger

## Possible Hazards

33% of the mixture consists of ingredient(s) of unknown acute toxicity.

#### **GHS HAZARD STATEMENTS**

Flammable Aerosol, category 1

Carcinogenicity, category 1A H350 May cause cancer. Eye Irritation, category 2A H319 Causes serious eye irritation. H222

Gases under Pressure; Compressed Gas H280 Contains gas under pressure; may explode if heated.

H340 Germ Cell Mutagenicity, category 1B May cause genetic defects.

STOT, Repeated Exposure, category 2 H373 May cause damage to organs through prolonged or repeated exposure.

Extremely flammable aerosol.

STOT, Single Exposure, category 3, NE H336 May cause drowsiness or dizziness.

Skin Irritation, category 2 H315 Causes skin irritation.

#### GHS LABEL PRECAUTIONARY STATEMENTS

P201 Obtain special instructions before use.

P210 Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. NO

SMOKING.

P211 Do not spray on an open flame or other ignition source.

P251 Do not pierce or burn, even after use. Date Printed: 11/08/2021 Page 2 / 8

P260 Do not breathe dust/fume/gas/mist/vapors/spray.

P264 Wash hands thoroughly after handling.
P271 Use only outdoors or in a well-ventilated area.

P280 Wear protective gloves/protective clothing/eye protection/face protection.

P302+P352 IF ON SKIN: Wash with plenty of soap and water.

P304+P340 IF INHALED: Remove person to fresh air and keep comfortable for breathing.

P305+P351+P338 IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present

and easy to do. Continue rinsing.

P308+P313 IF exposed or concerned: Get medical advice/attention.
P312 Call a POISON CENTER or doctor/physician if you feel unwell.

P321 For specific treatment see label.

P332+P313 If skin irritation occurs: Get medical advice/attention.
P337+P313 If eye irritation persists: Get medical advice/attention.
P362+P364 Take off contaminated clothing and wash it before reuse.
P403+P233 Store in a well-ventilated place. Keep container tightly closed.

P405 Store locked up.

P410+P403 Protect from sunlight. Store in a well-ventilated place.

P410+P412 Protect from sunlight. Do not expose to temperatures exceeding 50°C / 122°F.

P501 Dispose of contents/container in accordance with local, regional and national regulations.

## 3. Composition/Information On Ingredients

#### **HAZARDOUS SUBSTANCES**

| <u>Chemical Name</u>                   | CAS-No.    | <u>Wt.%</u><br><u>Range</u> | GHS Symbols           | GHS Statements             |
|--|------------|-----------------------------|-----------------------|----------------------------|
| Acetone                                | 67-64-1    | 25-50                       | GHS02-GHS07           | H225-319-332-336           |
| Propane                                | 74-98-6    | 10-25                       | GHS04                 | H280                       |
| n-Butane                               | 106-97-8   | 2.5-10                      | GHS04                 | H280                       |
| n-Butyl Acetate                        | 123-86-4   | 2.5-10                      | GHS02-GHS07           | H226-336                   |
| Barium Sulfate                         | 7727-43-7  | 2.5-10                      | GHS07                 | H332                       |
| Xylenes (o-, m-, p- Isomers)           | 1330-20-7  | 2.5-10                      | GHS02-GHS07           | H226-315-319-332-335       |
| Dimethyl Carbonate                     | 616-38-6   | 2.5-10                      | GHS02                 | H225                       |
| Naphtha, Petroleum, Hydrotreated Light | 64742-49-0 | 2.5-10                      | GHS07-GHS08           | H304-315-319-372           |
| Carbon Black                           | 1333-86-4  | 1.0-2.5                     | GHS08                 | H373                       |
| Propylene Glycol Monobutyl Ether       | 5131-66-8  | 1.0-2.5                     | GHS07                 | H302-315-319               |
| Ethylbenzene                           | 100-41-4   | 1.0-2.5                     | GHS02-GHS07           | H225-315-319-332           |
| Solvent Naphtha, Light Aromatic        | 64742-95-6 | 0.1-1.0                     | GHS07-GHS08           | H304-315-319-332-372       |
| Octane                                 | 111-65-9   | 0.1-1.0                     | GHS02-GHS07-<br>GHS08 | H225-304-315-336           |
| n-Heptane                              | 142-82-5   | 0.1-1.0                     | GHS02-GHS07-<br>GHS08 | H225-304-315-336           |
| Naphtha, Hydrotreated Heavy            | 64742-48-9 | 0.1-1.0                     | GHS08                 | H304-340-350               |
| Cobalt 2-Ethylhexanoate                | 136-52-7   | 0.1-1.0                     | GHS08                 | H317-319-334-350-360FD-372 |

The balance of the product is Nonhazardous.

#### 4. First-Aid Measures

**FIRST AID - EYE CONTACT:** Immediately flush eyes with plenty of water for at least 15 minutes holding eyelids open. Get medical attention. Do NOT allow rubbing of eyes or keeping eyes closed.

Date Printed: 11/08/2021 Page 3 / 8

FIRST AID - SKIN CONTACT: Wash skin with soap and water. Remove contaminated clothing. Get medical attention if irritation develops or persists.

**FIRST AID - INHALATION:** Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Get immediate medical attention. Do NOT use mouth-to-mouth resuscitation. If you experience difficulty in breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical assistance immediately.

**FIRST AID - INGESTION:** Aspiration hazard: Do not induce vomiting or give anything by mouth because this material can enter the lungs and cause severe lung damage. Get immediate medical attention. If swallowed, get medical attention.

## 5. Fire-fighting Measures

ADG HAZCHEM CODE: None

**EXTINGUISHING MEDIA:** Alcohol Film Forming Foam, Carbon Dioxide, Dry Chemical, Dry Sand, Water Fog

**UNUSUAL FIRE AND EXPLOSION HAZARDS:** FLASH POINT IS LESS THAN 20°F. EXTREMELY FLAMMABLE LIQUID AND VAPOR!Water spray may be ineffective. Closed containers may explode when exposed to extreme heat due to buildup of steam. Closed containers may explode when exposed to extreme heat. Vapors may form explosive mixtures with air. Vapors can travel to a source of ignition and flash back. Isolate from heat, electrical equipment, sparks and open flame. Perforation of the pressurized container may cause bursting of the can.

**SPECIAL FIREFIGHTING PROCEDURES:** Water may be used to cool closed containers to prevent pressure buildup and possible autoignition or explosion. Full protective equipment including self-contained breathing apparatus should be used. Evacuate area and fight fire from a safe distance. Use water spray to keep fire-exposed containers cool. Containers may explode when heated.

#### Accidental Release Measures

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED: Contain spilled liquid with sand or earth. DO NOT use combustible materials such as sawdust. Isolate the hazard area and deny entry to unnecessary and unprotected personnel. Remove all sources of ignition, ventilate area and remove with inert absorbent and non-sparking tools. Dispose of according to local, state (provincial) and federal regulations. Do not incinerate closed containers. Ventilate area, isolate spilled material, and remove with inert absorbent. Dispose of contaminated absorbent, container, and unused contents in accordance with local, state, and federal regulations.

## 7. Handling and Storage

**HANDLING:** Wash thoroughly after handling. Wash hands before eating. Remove contaminated clothing and launder before reuse. Use only with adequate ventilation. Follow all SDS and label precautions even after container is emptied because it may retain product residues. Avoid breathing fumes, vapors, or mist. Avoid contact with eyes, skin and clothing.

**STORAGE:** Keep containers tightly closed. Isolate from heat, electrical equipment, sparks and open flame. Contents under pressure. Do not store above 120°F. Store large quantities in buildings designed and protected for storage of flammable aerosols. Keep away from heat, sparks, flame and sources of ignition. Avoid excess heat. Product should be stored in tightly sealed containers and protected from heat, moisture, and foreign materials.

Advice on Safe Handling of Combustible Dust: No Information

## 8. Exposure Controls / Personal Protection

| Chemical Name                          | CAS-No.    | Weight % Less<br>Than | WHS WES TLV-TWA | WHS WES TLV-STEL |
|--|------------|-----------------------|-----------------|------------------|
| Acetone                                | 67-64-1    | 30.0                  | 250 ppm         | 500 ppm          |
| Propane                                | 74-98-6    | 20.0                  | N.E.            | N.E.             |
| n-Butane                               | 106-97-8   | 10.0                  | N.E.            | 1000 ppm         |
| n-Butyl Acetate                        | 123-86-4   | 10.0                  | 50 ppm          | 150 ppm          |
| Barium Sulfate                         | 7727-43-7  | 10.0                  | 5 mg/m3         | N.E.             |
| Xylenes (o-, m-, p- Isomers)           | 1330-20-7  | 5.0                   | 100 ppm         | 150 ppm          |
| Dimethyl Carbonate                     | 616-38-6   | 5.0                   | N.E.            | N.E.             |
| Naphtha, Petroleum, Hydrotreated Light | 64742-49-0 | 5.0                   | N.E.            | N.E.             |
| Carbon Black                           | 1333-86-4  | 5.0                   | 3 mg/m3         | N.E.             |
| Propylene Glycol Monobutyl Ether       | 5131-66-8  | 5.0                   | N.E.            | N.E.             |
| Ethylbenzene                           | 100-41-4   | 5.0                   | 20 ppm          | N.E.             |
| Solvent Naphtha, Light Aromatic        | 64742-95-6 | 1.0                   | N.E.            | N.E.             |
| n-Heptane                              | 142-82-5   | 1.0                   | 400 ppm         | 500 ppm          |
| Octane                                 | 111-65-9   | 1.0                   | 300 ppm         | N.E.             |
| Naphtha, Hydrotreated Heavy            | 64742-48-9 | 1.0                   | N.E.            | N.E.             |
| Cobalt 2-Ethylhexanoate                | 136-52-7   | 1.0                   | N.E.            | N.E.             |

Date Printed: 11/08/2021 Page 4 / 8

#### PERSONAL PROTECTION

**ENGINEERING CONTROLS:** Use process enclosures, local exhaust ventilation, or other engineering controls to control airborne levels below recommended exposure limits. Use explosion-proof ventilation equipment. Provide general dilution of local exhaust ventilation in volume and pattern to keep TLV of hazardous ingredients below acceptable limits. Prevent build-up of vapors by opening all doors and windows to achieve cross-ventilation.

RESPIRATORY PROTECTION: A respiratory protection program that meets OSHA 1910.134 and ANSI Z88.2 requirements must be followed whenever workplace conditions warrant a respirator's use. A NIOSH/MSHA approved air purifying respirator with organic vapor cartridge or canister may be permissible under certain circumstances where airborne concentrations are expected to exceed exposure limits. Wear an approved (or equivalent) full-facepiece airline respirator according to AS/NZS 1715-2009 and AS/NZS 1716-2012 in the positive pressure mode with emergency escape provisions. A respiratory protection program that meets AS/NZS 1715-2009 and AS/NZS 1716-2012 requirements must be followed whenever workplace conditions warrant a respirator's use. An approved air purifying respirator with organic vapor cartridge or canister according to AS/NZS 1715-2009 and AS/NZS 1716-2012 may be permissible under certain circumstances where airborne concentrations are expected to exceed exposure limits. Users of this product in industrial/OEM applications must use one of the following forms of respiratory protection:

- a. AS/NZS 1715-2009 and AS/NZS 1716-2012 compliant supplied-air respirator operated in pressure demand or continuous flow mode and equipped with a tight fitting facepiece
- b. AS/NZS 1715-2009 and AS/NZS 1716-2012 compliant air-purifying respirator equipped with a full facepiece and organic gas/vapor cartridges
- c. AS/NZS 1715-2009 and AS/NZS 1716-2012 compliant powered air-purifying respirator equipped with a full facepeice and organic gas/vapor cartridges.

SKIN PROTECTION: Use gloves to prevent prolonged skin contact. Nitrile or Neoprene gloves may afford adequate skin protection.

EYE PROTECTION: Use safety eyewear designed to protect against splash of liquids.

**OTHER PROTECTIVE EQUIPMENT:** Refer to safety supervisor or industrial hygienist for further guidance regarding types of personal protective equipment and their applications.

**HYGIENIC PRACTICES:** Wash thoroughly with soap and water before eating, drinking or smoking. Remove contaminated clothing immediately and launder before reuse.

Engineering Measures for Combustible Dust: No Information

## 9. Physical and Chemical Properties

**Physical State:** Appearance: Aerosolized Mist Liquid Odor: **Odor Threshold:** N.E. Solvent Like Specific Gravity: pH: 0.777 N.A. Freeze Point, °C: Viscosity: N.D. N.D. Partition Coefficient, n-octanol/ Solubility in Water: Slight N.D. water: Decomposition Temp., °C: N.D. Boiling Range, °C: **Explosive Limits, vol%:** -37 - 3,000 0.9 - 13.0Flammability: Supports Combustion Flash Point, °C: -96 **Evaporation Rate:** Auto-Ignition Temp., °C: Faster than Ether N.D. Vapor Density: Vapor Pressure: Heavier than Air N.D.

(See "Other information" Section for abbreviation legend)

## 10. Stability and Reactivity

Conditions to Avoid: Avoid temperatures above 120°F (49°C). Avoid all possible sources of ignition.

Incompatibility: Incompatible with strong oxidizing agents, strong acids and strong alkalies.

**Hazardous Decomposition:** By open flame, carbon monoxide and carbon dioxide. When heated to decomposition, it emits acrid smoke and irritating fumes. Contains solvents which may form carbon monoxide, carbon dioxide, and formaldehyde.

**Hazardous Polymerization:** Will not occur under normal conditions.

Stability: This product is stable under normal storage conditions.

## 11. Toxicological Information

EFFECTS OF OVEREXPOSURE - EYE CONTACT: Causes Serious Eye Irritation

**EFFECTS OF OVEREXPOSURE - SKIN CONTACT:** No Information

**EFFECTS OF OVEREXPOSURE - INHALATION:** Harmful if inhaled. High gas, vapor, mist or dust concentrations may be harmful if inhaled. Avoid breathing fumes, spray, vapors, or mist. High vapor concentrations are irritating to the eyes, nose, throat and lungs. Prolonged or excessive inhalation may cause respiratory tract irritation. Routine handling and application does not require use of respiratory protection; however, if air monitoring demonstrates vapor, mist, or dust levels above applicable limits, wear an appropriate,

Date Printed: 11/08/2021 Page 5 / 8

properly fitted respirator (meets AS/NZS 1715-2009 and AS/NZS 1716-2012 requirements) during handling and application. Follow respirator manufacturer's directions for respirator use.

EFFECTS OF OVEREXPOSURE - INGESTION: Harmful if swallowed.

EFFECTS OF OVEREXPOSURE - CHRONIC HAZARDS: May cause central nervous system disorder (e.g., narcosis involving a loss of coordination, weakness, fatigue, mental confusion, and blurred vision) and/or damage. High concentrations may lead to central nervous system effects (drowsiness, dizziness, nausea, headaches, paralysis, and blurred vision) and/or damage. Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Overexposure to xylene in laboratory animals has been associated with liver abnormalities, kidney, lung, spleen, eye and blood damage as well as reproductive disorders. Effects in humans, due to chronic overexposure, have included liver, cardiac abnormalities and nervous system damage. Contains carbon black. Chronic inflammation, lung fibrosis, and lung tumors have been observed in some rats experimentally exposed for long periods of time to excessive concentrations of carbon black and several insoluble fine dust particles. Tumors have not been observed in other animal species (i.e., mouse and hamster) under similar circumstances and study conditions. Epidemiological studies of North American workers show no evidence of clinically significant adverse health effects due to occupational exposure to carbon black.

Carbon black is listed as a Group 2B-"Possibly carcinogenic to humans" by IARC and is proposed to be listed as A4- "not classified as a human carcinogen" by the American Conference of Governmental Industrial Hygienists. Significant exposure is not anticipated during brush application or drying. Risk of overexposure depends on duration and level of exposure to dust from repeated sanding of surfaces or spray mist and the actual concentration of carbon black in the formula. IARC lists Ethylbenzene as a possible human carcinogen (group 2B).

PRIMARY ROUTE(S) OF ENTRY: Eye Contact, Ingestion, Inhalation, Skin Absorption, Skin Contact

#### **ACUTE TOXICITY VALUES**

The acute effects of this product have not been tested. Data on individual components are tabulated below:

| CAS-No.    | Chemical Name                          | Oral LD50        | Dermal LD50         | Vapor LC50      |
|------------|--|------------------|---------------------|-----------------|
| 67-64-1    | Acetone                                | 5800 mg/kg Rat   | >15700 mg/kg Rabbit | 50.1 mg/L Rat   |
| 106-97-8   | n-Butane                               | N.E.             | N.E.                | 658 mg/L Rat    |
| 123-86-4   | n-Butyl Acetate                        | 10768 mg/kg Rat  | >17600 mg/kg Rabbit | > 21 mg/L Rat   |
| 7727-43-7  | Barium Sulfate                         | 307000 mg/kg Rat | N.E.                | N.Ē.            |
| 1330-20-7  | Xylenes (o-, m-, p- Isomers)           | 3500 mg/kg Rat   | >4350 mg/kg Rabbit  | 29.08 mg/L Rat  |
| 616-38-6   | Dimethyl Carbonate                     | 13000 mg/kg Rat  | >5000 mg/kg Rabbit  | 140 mg/L Rat    |
| 64742-49-0 | Naphtha, Petroleum, Hydrotreated Light | >5000 mg/kg Rat  | >3160 mg/kg Rabbit  | >4951 mg/L Rat  |
| 1333-86-4  | Carbon Black                           | >15400 mg/kg Rat | N.E.                | N.E.            |
| 5131-66-8  | Propylene Glycol Monobutyl Ether       | 1900 mg/kg Rat   | >2000 mg/kg Rat     | N.E.            |
| 100-41-4   | Ethylbenzene                           | 3500 mg/kg Rat   | 15400 mg/kg Rabbit  | 17.4 mg/L Rat   |
| 64742-95-6 | Solvent Naphtha, Light Aromatic        | 8400 mg/kg Rat   | >2000 mg/kg Rabbit  | N.E.            |
| 111-65-9   | Octane                                 | N.E.             | N.E.                | >23.36 mg/L Rat |
| 142-82-5   | n-Heptane                              | N.E.             | 3000 mg/kg Rabbit   | 103 mg/L Rat    |
| 64742-48-9 | Naphtha, Hydrotreated Heavy            | >6000 mg/kg Rat  | >5000 mg/kg Rabbit  | N.E.            |
| 136-52-7   | Cobalt 2-Ethylhexanoate                | N.Ĕ.             | >5000 mg/kg Rabbit  | N.E.            |

N.E. - Not Established

## 12. Ecological Information

**ECOLOGICAL INFORMATION:** Product is a mixture of listed components.

## 13. Disposal Information

**DISPOSAL INFORMATION:** Do not incinerate closed containers. This product as supplied is a USEPA defined ignitable hazardous waste. Dispose of unusable product as a hazardous waste (D001) in accordance with local, state, and federal regulation.

Date Printed: 11/08/2021 Page 6 / 8

## 14. Transport Information

 Domestic (USDOT)
 International (IMDG)
 Air (IATA)
 ADG

 UN Number:
 N.A.
 1950
 1950
 1950

Proper Shipping Name:

Paint and Related Spray
Products in Ltd Qty

Aerosols
Aerosols, flammable
Aerosols

 Hazard Class:
 N.A.
 2
 2.1
 2.1

 Packing Group:
 N.A.
 N.A.
 N.A.
 N.A.
 N.A.

 Limited Quantity:
 Yes
 Yes
 Yes
 Yes

ADG Hazchem Code: None

## 15. Regulatory Information

#### **Montreal Protocol**

No Montreal Protocol components exist in this product.

## **Stockholm Convention**

No Stockholm Convention components exist in this product.

#### **Rotterdam Convention**

No Rotterdam Convention components exist in this product.

#### **MARPOL**

This product contains the following substances listed under the MARPOL regulations:

 Chemical Name
 CAS-No.

 Octane
 111-65-9

 n-Heptane
 142-82-5

 n-Nonane
 111-84-2

 Naphthalene
 91-20-3

#### **SUSMP**

This product contains the following substances classified as poisons as regulated by the Poisons Standard (SUSMP):

Chemical NameSchedule Number(s)Liquid HydrocarbonsSchedule 5

## **Capital Territories Environmental Regulations**

This product contains the following substances listed under the Australian Capital Territories Environmental Protection Regulation:

| <u>Chemical Name</u>         | <u>Schedule</u> | Schedule Name                        |
|------------------------------|-----------------|--------------------------------------|
| Xylenes (o-, m-, p- Isomers) | 3               | DOM - Organic Chemicals              |
| Ethylbenzene                 | 3               | Non-pesticide Anthropogenic Organics |
| Toluene                      | 3               | Non-pesticide Anthropogenic Organics |
| Benzene                      | 3               | Non-pesticide Anthropogenic Organics |

Date Printed: 11/08/2021 Page 7 / 8

## 16. Other Information

SDS REVISION DATE: 11/08/2021

REASON FOR REVISION: Product Composition Changed

Substance and/or Product Properties Changed in Section(s):

02 - Hazard Identification 16 - Other Information

Revision Statement(s) Changed

Legend:

N.A. - Not Applicable N.D. - Not Determined N.E. - Not Established

S.T.E.L. - Short Term Exposure Limit T.W.A. - Time Weighted Average W.E.S. - Workplace Exposure Standard W.H.S. - Work Health and Safety regulation

Rust-Oleum Corporation believes, to the best of its knowledge, information and belief, the information contained herein to be accurate and reliable as of the date of this safety data sheet. However, because the conditions of handling, use, and storage of these materials are beyond our control, we assume no responsibility or liability for personal injury or property damage incurred by the use of these materials. Rust-Oleum Corporation makes no warranty, expressed or implied, regarding the accuracy or reliability of the data or results obtained from their use. All materials may present unknown hazards and should be used with caution. The information and recommendations in this material safety data sheet are offered for the users' consideration and examination. It is the responsibility of the user to determine the final suitability of this information and to comply with all applicable international, federal, state, and local laws and regulations.

Date Printed: 11/08/2021 Page 8 / 8