

RUST-OLEUM®

CORPORATION

www.rustoleum.com

11 Hawthorn Pkwy., Vernon Hills, IL 60061 1-877-815-2536



RUSTEX RUST REMOVER

Directions for Use:

IMPORTANT:

1. Do not use when temperature is below 36°F. Excessive dew and humidity may prolong drying time and cause powdery buildup.
2. Do not use an airless sprayer or dilute this product.
3. Spray equipment should be flushed out with water after use. Clean brushes with water.
4. Avoid getting product on adjacent areas such as painted surfaces, concrete, masonry and stonework. If splashing occurs, flush immediately with water to remove.
5. DO NOT MIX THIS PRODUCT WITH ANY OTHER CHEMICALS.

DIRECTIONS-RUSTED & OLD METAL:

1. For heavily soiled surfaces use the Original Krud Kutter to remove excess oil, grease, and dirt.
2. Remove loose paint and heavy rust with a wire brush. Light rust need not be removed.
3. Apply directly to metal by brush, roller, mop, or low pressure sprayer. Heavy rust may need two applications.
4. Wait overnight after application, dust off any loose powder, and apply undercoat primer and paint.
5. Test small area for compatibility when using epoxy or latex paint.

If you have any questions or concerns regarding this product please contact Krud Kutter customer support at (800) 466-7126



www.rustoleum.com

11 Hawthorn Pkwy., Vernon Hills, IL 60061 1-877-815-2536

DIRECTIONS-GALVANIZED:

1. Apply one coat, and let stand for 30-60 minutes or until metal is etched.
2. Flush with water, avoiding damage to adjacent areas; or wipe to a smooth finish, let dry, and paint. Follow paint manufacturer's instructions for undercoats and topcoats.
3. Where rust is present apply one coat of Rustex to prep and etch the metal. Leave overnight, or until completely dry. Brush off any loose powder before painting

If you have any questions or concerns regarding this product please contact Krud Kutter customer support at (800) 466-7126